

Machine Protection - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
20026	Feature	New	Normal	Add a trip condition to RPU system.	Richard Neswold	05/25/2018 02:40 PM
19367	Feature	Assigned	Normal	Add another channel to PECL configuration	Richard Neswold	03/13/2018 02:08 PM
19366	Feature	Closed	Normal	Provide access to the frequency parameters in the PECL driver	Richard Neswold	03/15/2018 04:01 PM
18175	Feature	Assigned	Normal	Add access to decimation register	Richard Neswold	11/09/2017 11:17 AM
18174	Feature	Assigned	Normal	Add timestamp to trip information	Richard Neswold	11/09/2017 11:06 AM
18173	Feature	Closed	Normal	Detect overflow in averaging registers	Ning Liu	04/04/2018 10:32 AM
18171	Feature	Assigned	High	Add support for watchdog	Ning Liu	02/26/2018 10:15 AM
17994	Feature	New	High	Masking machine protection should generate an alarm		10/20/2017 10:54 AM
16756	Feature	Closed	Normal	Add BASIC CONTROL to V1495's register bank driver.	Richard Neswold	04/13/2018 02:28 PM
12038	Feature	Closed	Normal	After upgrading the firmware, the board should be reset.	Richard Neswold	03/23/2016 03:47 PM